



After the roof was cleaned with a 4,000 psi pressure washer (no photos) the roof was primed with an expensive marine primer used to prime the steel hulls of commercial ships exposed to seawater. The primer is red because of the iron oxide used to neutralize the rust. The primer was more expensive than the Bluestone Super Duty Aluminum Paint.





